

November 26, 2024 Public Hearing

The current proposal is: <u>Preservation Department – Item 8, LPC-25-01663</u>

23 East 9th Street – Greenwich Village Historic District Borough of Manhattan

To testify virtually, please join Zoom

Webinar ID: 161 709 3216 Passcode: 445660 By Phone: 646-558-8656 (NY) 877-853-5257 (Toll free) US 888-475-4499 (Toll free) **Note**: If you want to testify virtually on an item, join the Zoom webinar at the agenda's "Be Here by" time (about an hour in advance). When the Chair indicates it's time to testify, "raise your hand" via the Zoom app if you want to speak (*9 on the phone). Those who signed up in advance will be called first.

LPC PUBLIC HEARING

23 EAST 9TH ST TOWNHOUSE

DOCKET # LPC-25-01663 BUILDING HISTORY

PRIMARY FACADE ALTERATIONS

ROOF ALTERATIONS AND REAR YARD EXTENSIC

MOCK UP PHOTOS


PLANS

APPENDIX

	02
	07
NC	20
	36
	40
	46



23 EAST 9TH STREET - STREET VIEW



PROJECT LOCATION - GREENWICH VILLAGE HISTORIC DISTRICT


EAST 10TH STREET



PROJECT LOCATION - BLOCK PLAN



23 EAST 9TH STREET / Block Context



23 EAST 9TH STREET - AERIAL VIEW



PROJECT LOCATION - STREET VIEW FROM E 9TH STREET LOOKING EAST



PROJECT LOCATION - STREET VIEW FROM UNIVERSITY PLACE LOOKING WEST

23 EAST 9TH STREET / Building History




PHOTO DATE: 1913

SOURCE: NYPL

NOTES: Building built in 1843 by hardware merchant Aquila G. Stout.




PHOTO DATE: 1940

SOURCE: TAX PHOTO

NOTES:

Renovated in the early 1920's to include a store on the ground floor and apartments on the upper floors according to DOB records.

23 EAST 9TH STREET / Building History




PHOTO DATE: 1969

SOURCE: LPC Designation

NOTES:

Storefront removed and basement converted to an animal hospital between 1962 and 1965 according to DOB records.

> X3 CASEMENT *JALOUSIE REMOVED*

BRICK PARA

WALL EXTENDE

*CORNIC

REMOVED

COND FLOOR WINDOW AC PANEL ADDEE



PANEL ADDEI



530 9.9



PHOTO DATE: 1980

SOURCE: Tax Photo

NOTES: No DOB or LPC record of cornice removal or brick parapet extension.

23 EAST 9TH STREET / Building History



PHOTO DATE: 2024


SOURCE: Self-Taken

NOTES: Windows replaced in 2001

without LPC consent according to LPC violation 02-0392. No DOB or LPC record of brownstone base being changed. #23

This brick house, built in 1843 for Aquila G. Stout, mentioned above, retains its handsome yet simple Greek Revival cornice, small attic windows, and floor-length parlor windows. It appears to have been remodeled twice, once in the Nineteen-twenties when wood casement windows and iron flower box holders were installed. The basement entrance was evidently installed at this time when the stoop was removed. Earlier, the basement stonework had been painted and a narrow horizontal window added at eye level. Glass jalousies were installed in the little square windows of the fourth floor without removing the flower boxes.

Excerpt from Greenwich Village Historic District Designation Report, 1969



PRIMARY FACADE / Existing Brick Condition



EAST 9TH STREET FACADE



1. Brick repairs have been made with mismatched bricks





3. Lintels are in poor condition with the existing paint peeling



CONDITIONS STATEMENT:

The brick facade of the 181-year-old townhouse exhibits significant deterioration and inconsistencies due to extended neglect and inadequate maintenance. The damage is extensive and uniformly distributed across the entire facade, with numerous repairs made using bricks of varying colors, particularly noticeable around the window openings. A distinct outline remains where a portico entryway was infilled with non-matching bricks. Additionally, a parapet wall, constructed later with a much lighter-colored brick, is mismatched with the historic facade.

The brick surfaces have deteriorated severely over time, with many units showing signs of acute wear. Surface-level cracks and spalling are prevalent. Mortar joints are in various states of disrepair.

At the interior, the discoloration, efflorescence, failing mortar joints, evidence of repairs, decaying window frames, and damaged brick are consistent with that of continued water infiltration.





2. "Ghost" where entry portico and stoop were removed

4. Parapet built with insensitive materials

PRIMARY FACADE / Existing Brick Condition





5. Broken brick units and holes are common across the facade



7. Hairline cracks and poor brick face condition are typical




EAST 9TH STREET FACADE



6. Brownstone cracks

8. Large cracks have been poorly repaired

PRIMARY FACADE / Existing Brick Condition



PRIMARY FACADE WALL INTERIOR / Second Floor




PRIMARY FACADE WALL INTERIOR / First Floor

PRIMARY FACADE WALL INTERIOR / Third Floor





Hotel Martin / East 9th St and University Place / 1895





East 8th St. and University Looking North / 1895



37-41 East 9th St / 1895



10-14 East 8th St / 1895



IMAGES SOURCE:

Sailors' Snug Harbor Image Collection (New York University); MC 218; Box 1; New York University Archives, New York University Libraries



Hotel Martin / East 9th St and University Place / 1895



Hotel Lafayette / East 9th St and University Place / 1916

PRIMARY FACADE / Painted Brick Facade Precedents in Greewich Historic District



226 W 10th St



17 Gay St



66 Greenwich Ave



16 Christopher St



16 Charles St



176 MacDougal St



170 Waverly Pl



16-18 Gay St

PRIMARY FACADE / Painted Brick Facade Precedents in Greewich Historic District



175 MacDougal St



59 Grove St



55 Grove St



76 W Washington Pl



119 W 11th St



446 6th Ave



33 W 8th St



50 W 10th St



PRIMARY FACADE / Paint Mock-Ups



MOCK-UP LOCATION AT REAR FACADE



2 COATS OF KEIM SOLDADIT PAINT IN BM OC-146

PRODUCT SPECIFICATION:


To protect the aging masonry from further weathering and act as a waterproofing layer in place of the damaged fire skin; all masonry and stucco surfaces are to be painted with KEIM "Soldalit" silicate paint in BM OC-46 "Halo".

From the manufacturer's website: KEIM Soldalit is a highly specialized silicate facade paint based on a proven binder combination of silica sol and water glass. This binder combination allows silicate coatings not only on mineral but also on a wide range of organic substrates – directly and without additional bonding bridges. Filled and pigmented with weather-resistant fillers and purely inorganic pigments, it combines KEIM Soldalit all the benefits of classic dispersion silicate paint with the substrate versatility of organically bound paint systems. KEIM Soldalit also satisfies the requirements of DIN 18363 para. 2.4.1 "Dispersion silicate paint".

Note: The proposed coating is not reversible but is intended to provide the best protection against water intrusion while allowing the masonry to breathe as a vapor-permeable coating. As an alternate we would be willing to work with staff to find a reversible soft white coating

SURFACE PREP SPECIFICATION:

For paint to properly adhere to surface of masonry, prior to painting, masonry must be clean, dry, and dull. To achieve this existing masonry and stucco surfaces are to be prepped using a pressure washer with water pressure not to exceed 500psi to avoid surface damage. After the surface prep the wall will be given 48 hours to fully dry before painting.



CURRENT BRICK CONDITION IS VERY POOR

PRIMARY FACADE / Proposed Materials / Scale (1/8)" 1'-0"



PRIMARY FACADE / Front Entry Alterations



STREET VIEW



EXISTING RAILING




EXISTING ENTRY FROM STREET

EXISTING ENTRY





PRIMARY FACADE / Front Entry Alterations





EXISTING AREAWAY ELEVATION / Scale (1/4)" 1'-0"





PROPOSED AREAWAY PLAN / Scale (1/4)" 1'-0"




EXISTING HANDRAIL

EXISTING STAIRS -

GARDEN LEVEL

DN

PRIMARY FACADE / Areaway Alterations



EXISTING AREAWAY SECTION / Scale (1/4)" 1'-0"

PROPOSED AREAWAY SECTION / Scale (1/4)" 1'-0"





5TH AVE

23 EAST 9TH STREET

ROOF ALTERATIONS / Existing Conditions



EXISTING STAIR BULKHEAD / Looking East



EXISTING PARAPET WALL / Looking South Toward E 9th Street



EXISTING SKYLIGHT BULKHEADS / Looking North



EXISTING CHIMNEYS / Looking West



EXISTING SKYLIGHT BULKHEAD




EXISTING SKYLIGHT BULKHEAD

SIDE FACADE / Existing Conditions



VIEW FROM 9TH STREET


VIEW THROUGH GATE









ROOF ALTERATIONS AND REAR YARD ADDITION / EXISTING SITE PLAN / Scale (1/8)" 1'-0"













ROOF ALTERATIONS AND REAR YARD ADDITION / Existing Side (East) Elevation / Scale (1/8)" 1'-0"





ROOF ALTERATIONS AND REAR YARD ADDITION / Existing and Proposed Side (East) Elevations / Scale (1/16)" 1'-0"






PROPOSED SIDE ELEVATION

EXISTING SIDE ELEVATION

ROOF ALTERATIONS AND REAR YARD ADDITION / Proposed Building Section / Scale (1/8)" 1'-0"



REAR YARD ADDITION / Existing Conditions



EXISTING CONDITIONS / Basement




EXISTING CONDITIONS / First Floor



EXISTING CONDITIONS / Second and Third Floor

REAR YARD ADDITION / Existing Conditions



REAR WALL INTERIOR / Third Floor



REAR WALL INTERIOR / Second Floor



REAR WALL INTERIOR / First Floor

REAR YARD ADDITION / Existing Conditions



REAR YARD / Looking West



REAR YARD / Looking North



REAR YARD / Looking East



REAR YARD / Looking South


REAR YARD ADDITION / Proposed and Existing Rear Facade Elevations / Scale (1/8)" 1'-0"



REAR FACADE / Proposed Materials / Scale (1/8)" 1'-0"




1. KEIM soldalit masonry paint in BM-46 "Halo" will be used to coat all new and existing masonry surfaces including the stucco bulkhead, stucco side facades, garden wall, and all brickwork.



2. Benjamin Moore 2131-20 "Midnight" will be used to paint all metalwork and exterior wood which includes the roof terrace railings and windows



3. New bluestone coping at the existing parapet wall, extension parapet wall, and the new bulkhead.










SITE PLAN / 1/32" 1'-0"

 \bigcirc











С


SITE PLAN / 1/32" 1'-0"
















SITE PLAN / 1/32" 1'-0"




PROPOSED PLAN - CELLAR














PROPOSED PLAN - BASEMENT




DEMOLITION PLAN - FIRST FLOOR





PROPOSED PLAN - FIRST FLOOR






PROPOSED PLAN - SECOND FLOOR






PROPOSED PLAN - THIRD FLOOR



DEMOLITION PLAN - ROOF



PROPOSED PLAN - ROOF



SITE PLAN / 1/32" 1'-0"





November 26, 2024 Public Hearing

The current proposal is: <u>Preservation Department – Item 8, LPC-25-01663</u>

23 East 9th Street – Greenwich Village Historic District Borough of Manhattan

To testify virtually, please join Zoom

Webinar ID: 161 709 3216 Passcode: 445660 By Phone: 646-558-8656 (NY) 877-853-5257 (Toll free) US 888-475-4499 (Toll free) **Note**: If you want to testify virtually on an item, join the Zoom webinar at the agenda's "Be Here by" time (about an hour in advance). When the Chair indicates it's time to testify, "raise your hand" via the Zoom app if you want to speak (*9 on the phone). Those who signed up in advance will be called first.

APPENDIX

PRIMARY FACADE / Cornice Reconstruction




CORNICE FROM 1940 TAX PHOTO



CORNICE MODEL







CORNICE MODEL


p. 15

N


VIGNOLA PLATE 19 Proportions for the cornice recreation are based on plate 19 from Vignola's "Canon of the five orders of architecture" w. 1592.

Parte 31 NUMBER OF THE OWNER フ는 The way way way way way way way way way and and the lot in the last first when the start when the start of the Il modo di fare il capitello Ionico ancora che nella precente carta sia derignato con la piasta et profilo à piu chiàra intelligentia si deue tirrar due linee a perpendicolo duoi moduli lontano una dallalma le quali pastano per il centro de gli occhi delle uolute et sono chiamate Carbeni Tuna la uolusa deue essere alta 16 parti di modulo 8 restatio sopra l'occhio il quale è duoc parti et leisei restano di sono. Il modo col quale si fanno queste uolute é disegnato nella seguente carta et ui sara en: co breuenente serviro(per quanto comporte lo spatio) il modo con che si procede. Parte 4 хуща 10


PRIMARY FACADE / Cornice Reconstruction




ROOF ALTERATIONS AND REAR YARD ADDITION / Existing Building Section / Scale (1/8)" 1'-0"




ROOF ALTERATIONS / Wall types / Scale (1-1/2)" 1'-0"




WALL TYPE - REAR WALL RECONSTRUCTION



WALL TYPE - REAR EXTENSION NORTH WALL





WALL TYPE - BULKHEAD WALL





WALL TYPE - REAR EXTENSION EAST WALL


PRIMARY FACADE / Windows












REAR GARDEN WALL DETAIL ELEVATION / Scale (1/4)" 1'-0"



REAR GARDEN WALL DETAIL SECTION / Scale (1/2)" 1'-0"

MOCK UP / Construction Photos



ROOF BULKHEAD AND RAILING / Looking North



ROOF BULKHEAD AND RAILING / Looking South





ROOF BULKHEAD AND RAILING / Looking East



ROOF BULKHEAD AND RAILING / Looking East



REAR EXTENSION/ Looking South

REAR EXTENSION / Looking Down from Roof

















November 26, 2024 Public Hearing

The current proposal is: <u>Preservation Department – Item 8, LPC-25-01663</u>

23 East 9th Street – Greenwich Village Historic District Borough of Manhattan

To testify virtually, please join Zoom

Webinar ID: 161 709 3216 Passcode: 445660 By Phone: 646-558-8656 (NY) 877-853-5257 (Toll free) US 888-475-4499 (Toll free) **Note**: If you want to testify virtually on an item, join the Zoom webinar at the agenda's "Be Here by" time (about an hour in advance). When the Chair indicates it's time to testify, "raise your hand" via the Zoom app if you want to speak (*9 on the phone). Those who signed up in advance will be called first.