

The current proposal is:

Preservation Department – Item 3, LPC-25-01016

458 Broadway – SoHo-Cast Iron Historic District Borough of Manhattan

To testify virtually, please join Zoom

Webinar ID: 161 083 9543

Passcode: 620822

By Phone: 646-558-8656 (NY)

877-853-5257 (Toll free) US

888-475-4499 (Toll free)

Note: If you want to testify virtually on an item, join the Zoom webinar at the agenda's "Be Here by" time (about an hour in advance). When the Chair indicates it's time to testify, "raise your hand" via the Zoom app if you want to speak (*9 on the phone). Those who signed up in advance will be called first.

Proposal for Vault Light Cover Removal




458 Broadway Aka. 123 Grand St New York, NY 10013

Block: 232 Lot: 12

Proposal for Vault Light Cover Removal

Location

The property is located at the North-West corner of Block 232, at the South-East corner of the intersection of Broadway and Grand Street in the SoHo-Cast Iron Historic District.



458 BROADWAY: SIDEWALK VAULT REPLACEMENT - PHASE 1

CB102/LPC PRESENTATION

Proposal for Vault Light Cover Removal

Existing Conditions requiring repair








- Significant deterioration of steel structure due moisture infiltration from the sidewalk above
- Temporary shoring has been put in place in order to prevent movement or failure


Proposal for Vault Light Cover Removal


Proposed Work – North Sidewalk



Proposal for Vault Light Cover Removal


Proposed Work - North Sidewalk and Vault





Proposal for Vault Light Cover Removal

Proposed Work – North Sidewalk/Vault



Proposal for Vault Light Cover Removal

Photo from 1912




No vault light panels are visible in historic photos

Photo from the 1940s



Proposal for Vault Light Cover Removal

Current Conditions









Proposal for Vault Light Cover Removal

Existing cast iron vault light cover panels appear to function as framework for concrete wearing surface placement at some point in history.




Existing panels are in poor condition and will not serve as a viable component of the sidewalk wearing surface.



RE:

Proposal for Vault Light Cover Removal

Existing cast iron vault light cover panels are in very poor condition.





Proposal for Vault Light Cover Removal







- Vault light panels and/or diamond plate cover does not exist in the context of this block or surrounding area.
- New sidewalk vault light panel fabrication and installation estimated cost is in excess of \$100,000
- Removal of glass vault light covers will prevent the potential for tripping hazards and water infiltration into the interior of the vault below

Proposal for Vault Light Cover Removal

Excerpts from LPC Designation Report – Broadway & Grand St.





Broadway: East Side

Howard to Grand Street (Block 232)

All of the iron vault covers have been resurfaced or removed.

The sidewalks along this block are a mixture of materials:

##458 Sidewalk: Concrete with granite curbstones

Grand Street: South Side

Broadway to Crosby Street (Block 232)

The iron vault covers have been removed or resurfaced.

The sidewalk is concrete with bluestone curbs, but in some places the sidewalk is resurfaced with tarpaper and asphalt.

Proposal for Vault Light Cover Removal

THANK YOU FOR YOUR TIME AND CONSIDERATION

ANY QUESTIONS?







The current proposal is:

Preservation Department – Item 3, LPC-25-01016

458 Broadway – SoHo-Cast Iron Historic District Borough of Manhattan

To testify virtually, please join Zoom

Webinar ID: 161 083 9543

Passcode: 620822

By Phone: 646-558-8656 (NY)

877-853-5257 (Toll free) US

888-475-4499 (Toll free)

Note: If you want to testify virtually on an item, join the Zoom webinar at the agenda's "Be Here by" time (about an hour in advance). When the Chair indicates it's time to testify, "raise your hand" via the Zoom app if you want to speak (*9 on the phone). Those who signed up in advance will be called first.