

Beekman St and Front St

Pedestrian Access Improvements



Background


- Uncontrolled crossing without warning signage on Beekman St
- Denied for an all-way stop in June 2017
- 2 pedestrian KSI, both in 2013

Location

- High density commercial activity in the Seaport District
- Historic area with cobblestone streets



Before: Beekman and Front St



Improvements

- Add pedestrian warning signs at decorative crossings on Beekman St at Front St
- Add 15 feet of daylighting

Benefits

- Makes crossing pedestrians more visible to vehicles
- Formalizes crossings